

S.B. No.	Title	Issue/ Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
01	Aileron Control Circuit Inspection	1 11.5.82	T67A	Mandatory	003-01-93	CAA
02	Exhaust Heat Exchanger Asbestos Seal Inspection	1 21.6.82	T67A	Mandatory	004-01-93	CAA
02	Exhaust Heat Exchanger Asbestos Seal Inspection	2 6.7.89	T67A	Mandatory	004-01-93	CAA
03	Bendix Magneto Impulse Couplings - Ref Lycoming SB464/Bendix SB 623	1 13.10.82	T67A	Minor	N/A	SAL
04	Inspection of Control Column	1 10.2.83	T67A	Recommended	N/A	SAL
05	Inspection of Mainplane Walkways	1 10.2.83	T67A	Recommended	N/A	SAL
06	Rudder Turnbuckles - Wire Locking	1 1.11.83	T67A	Recommended	N/A	SAL
07	Oil Level Limitations for Aerobatic Flight	1 6.1.84	T67A	Mandatory	005-01-93	CAA
07	Oil Level Limitations for Aerobatic Flight	2 3.5.84	T67A	Mandatory	005-01-93	CAA
08	Inspection of Rudder/Toe Brake Assembly for Security of Hexagon Socket Cap Screws	1 3.8.84	T67B, T67M	Recommended	N/A	SAL
08	Inspection of Rudder/Toe Brake Assembly for Security of Hexagon Socket Cap Screws	2 20.11.85	T67B, T67C, T67M, T67M-MkII, T67M200	Mandatory	013-11-85	CAA
09	NOT ISSUED	-	-	-	-	-
10	Inspection of Tailplane Attachment Bolts - T67 Aircraft	1 29.8.85	T67B, T67M	Mandatory	006-01-93	CAA
10	Inspection of Tailplane Attachment Bolts - T67 Aircraft	2 11.4.88	T67B, T67C, T67M, T67M-MkII, T67M200	Mandatory	006-01-93	CAA
11	NOT ISSUED	-	-	-	-	-
12	Inspection for Battery Acid Leakage and/or Damage T67M	1 3.4.86	T67M Pre-Mod 117 or Pre-Mod 114B	Mandatory	011-05-87	CAA
13	Main Undercarriage Top Mounting Block	1 5.1.87	T67B, T67M, T67M-MkII, T67M200 Post Mod M198A	Mandatory	003-05-87	CAA
14	Bearings in Control Column Aileron Tie Rod	1 5.1.87	T67A, T67B, T67M, T67M-MkII, T67M200	Mandatory	004-05-87	CAA

S.B. No.	Title	Issue/ Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
14	Bearings in Control Column Aileron Tie Rod	2 19.2.87	T67A,T67B, T67M, T67M-MkII, T67M200	Mandatory	004-05-87	CAA
14	Bearings in Control Column Aileron Tie Rod	3 14.3.88	T67A,T67B, T67M, T67M-MkII, T67M200	Mandatory	004-05-87	CAA
15	Rudder Pedal to Sidewall and Rudder Cable Clearances	1 5.1.87	All GRP T67 A/C Works Nos 2000 to 2020 and 2023 to 2034	Mandatory	005-05-87	CAA
16	NOT ISSUED	-	-	-	-	-
17	T67A Aft Tailplane Location Brackets	1 27.11.86	T67A	Mandatory	012-05-87	CAA
18	Inspection of Flap Centre Drive Brackets	1 26.1.87	T67A, T67B, T67C, T67M. T67M-MkII, T67M200	Mandatory	007-01-93	CAA
19	Deletion of Mod M067 shoulder Strap Extensions from T67A Aircraft	1 24.4.87	T67A, with Mod M067 fitted	Mandatory	013-07-87	CAA
20	Service Life - T67 GRP Aircraft	1 21.12.87	T67B, T67C, T67M, T67M-MkII, T67M200	Mandatory	008-01-93	CAA
21	Special Inspection to Engine Mounting Frames T67 GRP 160 HP and 200 HP aircraft. pre Mod M278A and Mod M278B respectively	1 21.12.87	T67C, T67M-MkII, T67M200	Additional Maintenance Information	N/A	SAL
22	Checks on Fuel Flow: Aerobatic Flight	1 28.4.88	T67C Post Mod M156, T67M-MkII, T67M200	Mandatory	AD not issued	CAA
22	Checks on Fuel Flow: Aerobatic Flight	2 16.1.89	T67C Post Mod M156, T67M-MkII, T67M200	Optional	N/A	SAL
22	Checks on Fuel Flow: Aerobatic Flight - Mod M567 Ref.	3 11.4.94	T67C Post Mod M156, T67M-MkII, T67M200	Mandatory	004-04-94	CAA
23	T67M200 Propeller Daily Inspection - Ref Hoffmann SB E6.	1 20.6.88	All T67M200 fitted with Hoffmann HO-V123K-V/180R	Mandatory	LBA(AD) LTA88-20	CAA
23	T67M200 Propeller Daily Inspection - Ref Hoffmann SB E6.	2 26.05.04	All T67M200 fitted with Hoffmann HO-V123K-V/180R	Mandatory by LBA	LBA(AD) LTA88-20	CAA
24	T67M200 Propeller Fitting	1 6.7.88	T67M200 prior to Construction No. 2058	Mandatory	009-01-93	CAA
25	Flight in Thunderstorm and Lightning Activity	1 6.7.88	T67B, T67C Series, T67M, T67M-MkII, T67M200 with Mod M272B or M177B fitted	Mandatory	010-01-93	CAA
25	Flight in Thunderstorm and Lightning Activity	2 8.11.89	T67B, T67C Series, T67M, T67M-MkII, T67M200 with Mod M272B or M177B fitted	Mandatory	010-01-93	CAA

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
26	T.B.O. - Propeller R.P.M. Governors - Ref Woodward SB No.33580A	1 3.10.88	T67M, T67M-MkII, T67M200	Recommended	N/A	SAL
27	Hoffmann Propeller - T.B.O - Ref Hoffmann SB No. EB1J	1 3.10.88	T67M, T67Mk-II	Recommended	N/A	SAL
28	Special Inspection - A125D/66 Stiffnuts	1 16.1.89	Construction Nos.2045-2051, 2052-2061,2063	Mandatory	011-01-93	CAA
29	Recall of Aeroquip 601 Type Hose - Ref Aeroquip S.B. No 002 R1	1 22.3.89	T67C, T67M-MkII, T67M200	Mandatory	024-03-89	CAA
30	Aileron Flettner Strips	1 24.5.89	T67M, T67M-MkII T67M200 except Works Nos.2043,2062,2066 and subsequent.	Optional	N/A	SAL
31	Special Inspection - Safety Harness (Negative 'G' Strap)	1 7.6.89	Part A: Works Nos 2000,2002-2004, 2008-2011,2013-2018, 2020-2033 2035-2063,2066-2069,2075,2078 (Part B) 2064,2065,2070-2074,2076,2077,2079 and subs.	Mandatory	012-01-93	CAA
32	King Radio KCS 55A Slaved Gyrocompass System - Erroneous Readings	1 18.7.89	T67M-MkII, T67M200	Mandatory	013-01-93	CAA
32	King Radio KCS 55A Slaved Gyrocompass System - Erroneous Readings	2 7.11.89	T67M-MkII, T67M200	Mandatory	013-01-93	CAA
33	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft (NOT NOW AVAILABLE)	1 -	T67M except Works No.1999, T67B, T67C Series, T67M-MkII, T67M200 Pre Mod M412	Mandatory	014-01-93	CAA
33	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	2 27.8.89	T67M except Works No.1999, T67B, T67C Series, T67M-MkII, T67M200 Pre Mod M412	Mandatory	014-01-93	CAA
33	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	3 9.11.92	T67M except Works No.1999, T67B, T67C Series, T67M-MkII, T67M200 Pre Mod M412	Mandatory	014-01-93	CAA
33	Special Inspection of Rudder Bar Pedal Support Lugs on T67 GRP Series Aircraft	4 18.7.95	T67M except Works No.1999, T67B, T67C Series, T67M-MkII, T67M200 Pre Mod M412	Mandatory	014-01-93	CAA
34	Rudder Upper and Lower Hinge Support Angles - Inspection	1 7.11.89	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200	Mandatory	015-01-93	CAA
35	Wing Rear Spar	1 25.6.90	T67A	Additional Maintenance Information	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
35	Wing Rear Spar Inspection T67A aircraft.	2 13.1.97	T67A	Essential	N/A	SAL
36	Inspection of Nose Undercarriage Sliding Leg Weld	1 11.6.90	Pre Mod M468, T67B, T67C Series, T67M T67M-MkII, T67M200	Mandatory	018-06-90	CAA
37	Inspection of Main Undercarriage Torque Link Bolts	1 11.7.91	Pre Mod M468 T67B, T67C Series, T67M, T67M-MkII, T67M200	Mandatory	016-01-93	CAA
38	Extension of Fuel Vent Pipes (Wing Tank Aircraft Only)	1 10.4.92	Works Nos.2017, 2018, 2021-2022, 2027,2031-2033, 2038-2052, 2054-2061,2066-2069,2075 -2076, 2078	Optional	N/A	SAL
39	Inspection of Wing Rear Spar Top Surface to Fuselage Fairing Clearance	1 6.4.92	T67B, T67C Series, T67M, T67M-MkII, T67M200 except Works Nos.2074,2077, 2081,2083 2087 2099-2101.	Optional	N/A	SAL
40	Special Inspection of Throttle Cable - T67A/C Aircraft	1 18.3.92	All T67C Aircraft	Mandatory	017-01-93	CAA
40	Special Inspection of Throttle Cable - T67C A/C Aircraft	2 9.11.92	All T67C Aircraft pre Mod 480	Mandatory	017-01-93	CAA
41	Special Inspection of Throttle Cable - T67 GRP Aircraft Except T67C	1 9.11.92	All T67B, T67M, T67Mk-II, T67M200	Mandatory	018-01-93	CAA
41	Special Inspection of Throttle Cable - T67B Aircraft	2 30.1.95	All T67B A/C	Mandatory	018-01-93	CAA
42	Inspection to Aileron Support Rib Outboard (Rib 8)	1 8.1.93	All T67B, T67C, T67M, T67Mk-II, T67M200, T67M260 Mod M490A only	Mandatory	002-01-93	CAA
43	Engine Settings to Alleviate Engine Stop in Spin	1 2.3.93	T67C Series	Mandatory	015-03-93	CAA
43	Engine Settings to Alleviate Engine Stop in Spin	2 5.3.93	T67C Series	Mandatory	015-03-93	CAA
44	Check on Clearance between Forward U/C Leg and Engine Mounting Frame	1 10.3.94	Post Mod M468 T67C, T67M-MkII	Mandatory	004-03-94	CAA
45	T67A Centre Console Inspection	1 29.3.94	All T67A & T67M Works No 1999	Recommended	N/A	SAL
46	Split Canopy Locating Lug Re-Profile	1 29.3.94	T67C, T67M, T67M200 Post Mod M129 T67M-MkII, T67M260, T67M260-T3A	Recommended	N/A	SAL
46	Split Canopy Locating Lug Re-Profile	2 18.4.94	T67C, T67M, T67M200 Post Mod M129 T67M-MkII, T67M260, T67M260-T3A	Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
47	Static System Blockage	1 12.8.94	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Advisory	N/A	SAL
48	Windscreen De-misting Duct Routing Check	1 1.3.94	Pre Mod M515 T67B, T67C, T67M, T67M-MkII T67M200	Mandatory	011-03-94	CAA
49	Rudder Mechanism to Fuel Pipe Clearance Check	1 12.8.94	T67C Post Mod M156, T67M-MkII T67M200, T67M260, T67M260-T3A	Advisory	N/A	SAL
50	Inspection of Port Throttle Limit Stop Bolts	1 29.3.94	T67B, T67C Series T67M, T67M-MkII, T67M200	Advisory	N/A	SAL
51	Inspection of Rudder Cable to Link Plate Socket Head Cap Screw	1 29.3.94	T67B, T67C Series, T67M Post Mod M95 T67M-MkII T67M200, T67M260, T67M260-T3A	Mandatory	015-03-94	CAA
52	Elevator Horn Water Ingress - T67 Aircraft	1 27.5.94	T67B, T67C Series, T67M, T67-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	010-05-94	CAA
52	Elevator Horn Water Ingress - T67 Aircraft	2 27.6.94	T67B, T67C Series, T67M, T67-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	010-05-94	CAA
52	Elevator Horn Water Ingress - T67 Aircraft	3 6.3.96	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	010-05-94	CAA
53	Inspection of Air Injector Box Auxiliary Intake Door Spring Attachment	1 1.3.94	All T67M260-T3A Type A/C	Essential	N/A	SAL
54	Inspection of Wing Fuel Tank Drain Valves	1 26.5.94	T67M-MkII, T67M260-T3A	Mandatory	011-05-94	CAA
55	Special Inspection of Throttle Cable - T67 GRP Aircraft Except T67C	1 19.4.94	T67B, T67C (Pre Mod M480) T67M, T67M-MkII, T67M200	Mandatory	005-04-94	CAA
55	Special Inspection of Throttle Cable - T67 GRP Aircraft	2 22.4.94	T67C (Pre Mod M480) T67M, T67M-MkII, T67M200	Mandatory	005-04-94	CAA
55	Special Inspection of Throttle Cable - T67 160/200 HP aircraft	3 1.12.94	T67C (Pre Mod M480) T67M, T67M-MkII, T67M200	Mandatory	005-04-94	CAA
55	Special Inspection of Throttle Cable - T67 160/200 HP aircraft	4 24.1.95	T67C (Pre Mod M480) T67M, T67M-MkII, T67M200	Mandatory	005-04-94	CAA
56	Inspection of Air Intake Box By-Pass Flap Hinge	1 14.9.94	All T67M, T67M-MkII, T67M200	Recommended	N/A	SAL
56	Inspection of Air Intake Box By-Pass Flap Hinge	2 17.7.98	Pre Mod M595 T67M & T67M-MkII T67M200	Highly Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
57	Inspection of Rear Canopy Slide Rail Assembly	1 1.12.94	T67C, T67M T67M200, (All Post Mod M129) T67M-MkII, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
58	Fairey Undercarriage Inspection	1 20.6.94	All T67C T67M-MKII Post Mod 468, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
59	NOT ISSUED	-	-	-	-	-
60	Isolation of Low Fuel Sensor Units	1 14.9.94	All T67M260-T3A	Mandatory	009-09-94	CAA
61	Fuel System Maintenance	1 2.11.94	T67C Post Mod M156 T67M-MKII, T67M200, T67M260 T67M260-T3A	Highly Recommended	N/A	SAL
62	Flap Lever Proof Test	1 29.11.94	All T67M260-T3A	Mandatory	005-11-94	CAA
63	Inspection of Fuel System Joints	1 25.11.94	All T67M260-T3A	Recommended	N/A	SAL
64	Inspection of Elevator Bearing Plate	1 25.11.94	All T67M260-T3A	Mandatory	006-11-94	CAA
65	Nose Landing Gear Inspection and Modification	1 1.12.94	All T67 Post Mod M468 A/C, T67M260-T3A and all T67M260 A/C	Mandatory	001-12-94	CAA
66	NOT ISSUED	-	-	-	-	-
67	Inspection of Landing/Taxi Light Supply Cable Routing	1 2.2.95	All T67A, T67B, T67C Series T67M (not inc Works No.1999) & T67M-MkII	Recommended	N/A	SAL
68	Canopy Latch Correct Operation Inspection	1 31.3.95	T67C, T67M, T67M200 All Post Mod M129 (Split Canopy), T67M-MkII, T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
68	Canopy Latch Correct Operation Inspection	2 28.11.95	T67C, T67M, T67M200 All Post Mod M129 (Split Canopy), T67M-MkII, T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
68	Canopy Latch Correct Operation Inspection	3 20.6.96	T67C, T67M, T67M200 All Post Mod M129 (Split Canopy), T67M-MkII, T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
68	Canopy Latch Correct Operation Inspection	4 27.9.97	T67C, T67M, T67M200 All Post Mod M129 (Split Canopy), T67M-MkII, T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
68	Canopy Latch Correct Operation Inspection	5 17.7.98	T67M-MkII, T67M260 T67M260-T3A & any T67C, T67M & T67M200 A/C Post Mod M129/M129B (Split Canopy)	Highly Recommended	N/A	SAL
69	Inspection of Electric Trim Switch Holder	1 2.2.95	T67 GRP A/C Post Mod M443 T67M260-T3A	Recommended	N/A	SAL
70	Inspection of Manifold/Pressure Gauge to Pipe Connections	1 27.3.95	T67M, T67M-MkII, T67M200 T67M260 & T67M260-T3A	Mandatory	012-03-95	CAA
71	Inspection of Rudder Pedal Layshaft Mounting Brackets	1 2.2.95	All T67M260-T3A A/C	Highly Recommended	N/A	SAL
71	Inspection of Rudder Pedal Layshaft Mounting Brackets	2 12.8.96	T67M260-T3A & T67M260 Pre Mod M720 A/C	Highly Recommended	N/A	SAL
72	Inspection of Thermostatic Bypass Valves - Ref Lycoming S.B. No.518	1 3.2.95	T67M260-T3A A/C	Mandatory by Textron Lycoming	N/A	SAL
72	Inspection of Thermostatic Bypass Valves	2 9.2.95	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Mandatory by Textron Lycoming	N/A	SAL
73	Inspection of Left, Right and Tail Navigation Light Lens Gaskets	1 8.3.95	A) T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260 T67M260-T3A B) T67C Series, T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
74	Inspection of Routing of Upper Spark Plug Leads	1 8.3.95	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
74	Inspection of Routing of Upper Spark Plug Leads	2 31.3.95	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
75	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	1 8.3.95	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
75	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	2 6.4.95	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
75	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	3 2.6.95	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
75	Inspection of Rudder Pedal Slider/Heater Distribution Box Clearance	4 02.10.02	T67M260 Works Nos 2072, 2234 to 2260 & T67M260-T3A Works Nos. 2109, 2110, 2123 to 2133	Highly Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
76	Inspection of Wiring Looms in Centre Console and at Wing Main Spar	1 8.3.95	T67M260-T3A	Recommended	N/A	SAL
77	Inspection of Oil Cooler Duct to Engine Mounting Frame Clearance	1 8.3.95	T67M260-T3A Pre Mod M628	Recommended	N/A	SAL
78	Inspection of Rudder Cables and their Fairlead Pulleys	1 27.3.95	T67C & T67M-MkII (Post Mods M419 & M456) T67M260 & T67M260-T3A	Recommended	N/A	SAL
78	Inspection of Rudder Cables and their Fairlead Pulleys	2 30.6.95	T67C & T67M-MkII (Post Mods M419 & M456) T67M260 & T67M260-T3A	Recommended	N/A	SAL
78	Inspection of Rudder Cables and their Fairlead Pulleys	3 20.10.96	T67C & T67M-MkII (Post Mods M419 & M456) T67M260 & T67M260-T3A (Pre Mod M670)	Recommended	N/A	SAL
79	Inspection of Control Column to Seat Clearance and Seat Attachment Integrity	1 31.3.95	T67C, T67M-MkII (Post Mod M445), T67M260 & T67M260-T3A	Mandatory	008-04-95	CAA
79	Inspection of Control Column to Seat Clearance and Seat Attachment Integrity	2 2.4.96	T67M Works No.2004 (Post Mod M401A), T67C, T67M-MkII (Post Mod M445), T67M260 & T67M260-T3A	Mandatory	008-04-95	CAA
80	Inspection of Trim Cable Protective Sleeves (NOT NOW AVAILABLE)	1 5.7.96	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
80	Inspection of Trim Cable Protective Sleeves	2 15.1.97	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
81	Inspection and Replacement of Aluminium Hinge Injector Air Intake Duct Auxiliary Intake Door	1 5.7.96	T67M260-T3A	Highly Recommended	N/A	SAL
82	Inspection of wing walkway areas (NOT NOW AVAILABLE)	1 18.7.95	T67B, T67C Series, T67M, T67M-MkII & T67M200	Mandatory	009-07-95	CAA
82	Inspection of wing walkway areas	2 20.1.00	T67B, T67C Series, T67M, T67M-MkII & T67M200, T67M260 Works Nos 2234 & 2235 only), T67M260-T3A	Mandatory	009-07-95	CAA
82	Inspection of wing walkway areas	3 01.07.06	T67B, T67C Series, T67M, T67M-MkII & T67M200, T67M260 & T67M260-T3A prior to works number 2265. Not applicable Post Mod M827C repaired aircraft.	Subject of an Airworthiness Directive	009-07-95	CAA
82	Inspection of wing walkway areas	4 15.12.06	T67B, T67C Series, T67M, T67M-MkII & T67M200, T67M260 & T67M260-T3A prior to works number 2265. Not applicable Post Mod M827C repaired aircraft.	Subject of an Airworthiness Directive	009-07-95	CAA

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
83	Inspection for Foul Between No.2 Rudder Pedal Pad Pivot and Nosewheel Steering Rod Arm	1 17.2.96	T67B, T67C Series, T67M (Not Works No.1999), T67M-MkII, T67M200, T67M260 & T67M260-T3A	Mandatory	006-02-96	CAA
83	Inspection for Foul Between No.2 Rudder Pedal Pad Pivot and Nosewheel Steering Rod Arm	2 6.3.96	T67B, T67C Series, T67M (Not Works No.1999), T67M-MkII, T67M200, T67M260 & T67M260-T3A	Mandatory	006-02-96	CAA
84	Inspection of Rib 2 lower flange bond to wing skin	1 27.7.95	T67M260 & T67M260-T3A	Mandatory	010-07-95	CAA
84	Inspection of Rib 2 lower flange bond to wing skin	2 9.3.99	T67M260-T3A Serial/Works Nos.2153/92-0657, 2154/92-0658, 2171/93-0567, 2109/92-0625, 2132/92-0636, 2137/92-0641, 2138/92-0642.	Mandatory	010-07-95	CAA
85	Inspection for axle burrs and revised mainwheel torque instructions	1 27.7.95	T67B, T67C Series, T67M, T67M-MkII, T67M200 (All Post Mod M468 - Fairey Hydraulics Undercarriage, T67M260 & T67M260-T3A	Recommended	N/A	SAL
85	Inspection for axle burrs and revised mainwheel torque instructions	2 11.7.97	T67B, T67C Series, T67M, T67M-MkII, T67M200 (All Post Mod M468 - Fairey Hydraulics Undercarriage, T67M260 & T67M260-T3A	Recommended	N/A	SAL
86	Inspection of Fuselage Drain Holes	1 5.7.96	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
87	Reduced Structural Temperature Limitation from 55°C to 50°C and Prohibited Flight Temperature Limitation from 65°C to 55°C	1 4.9.95	T67M260 & T67M260-T3A	Mandatory	002-09-95	CAA
87	Reduced Structural Temperature Limitation from 55°C to 50°C and Prohibited Flight Temperature Limitation from 65°C to 55°C	2 20.9.95	T67M260 & T67M260-T3A	Mandatory	002-09-95	CAA
88	Rudder Pedal to Mixture Lever Potential Foul	1 29.8.96	T67M260 & T67M260-T3A Pre Mod M687 standard	Mandatory	007-08-95	CAA
88	Rudder Pedal to Mixture Lever Potential Foul	2 2.10.96	T67M260 & T67M260-T3A Pre Mod M687 standard	Mandatory	007-08-95	CAA
89	Additional Aileron Trim Tab Requirement	1 1.2.96	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260 T67M260-T3A	Recommended	N/A	SAL
90	Installation of an Air Intake Flow Divider to Eliminate Vibration & Noise in the Air Conditioning Condenser	1 17.2.96	T67M260 & T67M260-T3A with air con installed (Post Mod M501A)	Recommended	N/A	SAL
91	Inspection of Torque Link Mounting Lugs SAB Nose Wheel Leg	1 19.4.96	T67A, T67B, T67C Series, T67M, T67M-MkII and T67M200. All Pre Mod M468, ie SAB undercarriaged aircraft.	Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
92	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, Plus Vent Pipe Inlet Re-Orientation	1 01.02.96	T67M260-T3A Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233	Highly Recommended	N/A	SAL
92	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, Plus Vent Pipe Inlet Re-Orientation	2 18.02.05	T67M260-T3A Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233 Actions 1, 2.1 & 3. T67C wing tank (Post Mod M156) only, T67M-MkII, T67M200 & T67M260 action 2.2.	Highly Recommended	N/A	SAL
92	Inspection and Rectification of Fuel Vent and Hydraulic Reservoir Tube, Plus Vent Pipe Inlet Re-Orientation	3 04.09.07	T67M260-T3A Works Nos 2109, 2110, 2123 to 2128, 2130 to 2158, 2160 to 2233 Actions 1, 2.1 & 3. T67C wing tank (Post Mod M156) only, T67M-MkII, T67M200 & T67M260 action 2.2.	Highly Recommended	N/A	SACL
93	Inspection and Identification of Alternator Capacitor	1 5.7.96	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260-T3A	Highly Recommended	N/A	SAL
94	Inspection of Elevator Pushrod to Control Column assembly Pivot Bolt to Seat Clearance	1 5.7.96	T67M260-T3A Pre Mod M695 aircraft	Mandatory	007-07-96	CAA
95	Inspection of Throttle Cable Mounting Bracket.	1 19.4.96	T67M T67M-MkII	Recommended	N/A	SAL
96	Inspection and Replacement of Trim Wheel Thrust Washers	1 1.10.96	T67C Post Mod M443, T67M260 & T67M260-T3A	Recommended	N/A	SAL
97	Inspection of Engine Wiring for Chafing	1 19.4.96	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
98	Inspection and Rectification of Air Conditioning Compressor Alignment	1 29.2.96	T67M260-T3A Nos 2109, 2110, 2123 to 2158	Recommended	N/A	SAL
98	Inspection and Rectification of Air Conditioning Compressor Alignment	2 2.4.96	T67M260-T3A Nos 2109, 2110, 2123 to 2148	Recommended	N/A	SAL
99	Inspection and Rectification of Rudder Pedal Sliders	1 5.7.96	T67B, T67C Series T67M (Not Works No.1999) T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
99	Inspection and Rectification of Rudder Pedal Sliders	2 12.5.96	T67B, T67C Series, T67M (Not Works No.1999), T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL

S.B. No.	Title	Issue/ Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
99	Inspection and Rectification of Rudder Pedal Sliders	3 24.6.97	T67B, T67C Series, T67M (Not Works No.1999) T67M-MkII, T67M200 T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
99	Inspection and Rectification of Rudder Pedal Sliders	4 27.9.97	T67B, T67C Series, T67M (Not Works No.1999) T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
100	Water Ingress into Cockpit from ECS Frame 2 Bay	1 6.3.96	T67M260-T3A Post Mod M501A A/C	Highly Recommended	N/A	SAL
100	Water Ingress into Cockpit from ECS Frame 2 Bay	2 10.4.96	T67M260-T3A Post Mod M501A, Pre Mod 680B A/C	Highly Recommended	N/A	SAL
101	Inspection and Replacement of Flap Torque Tube Bearing at Rib 2	1 19.4.96	T67B, T67C Series, T67M, T67M-MkII (Pre Mod M519), T67M200	Recommended	N/A	SAL
102	Inspection of and Wiring of Roll Pin on Fuel Selector	1 29.2.96	T67M260 & T67M260-T3A	Mandatory	007-02-96	CAA
103	Inspection of Outboard Elevator Hinge Pivot Bush.	1 24.6.09	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
104	Inspection of bonding braid from flap torque tube pivot aft seat mounting tube lower bolt.	1 11.9.98	T67B, T67C Series, T67M, T67M-MkII T67M200 T67M260-T3, T67M260-T3A Pre Mod M721	Highly Recommended	N/A	SAL
105	Inspection of control surfaces for rubbing marks.	1 13.1.96	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
106	Inspection of Brake Cylinder for Correct Stroke	1 2.5.96	T67M260 & T67M260-T3A	Mandatory	005-04-96	CAA
107	Inspection of mixture lever	1 13.2.98	T67M260 & T67M260-T3A	Highly Recommended	N/A	SAL
108	Maintenance of crossover valve for correct operation	1 19.12.96	T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Recommended	N/A	N/A
109	Inspection of brake caliper bolts	1 30.8.96	T67M260-T3A	Recommended	N/A	SAL
110	Inspection and re-routing of air conditioning wiring	1 11.9.98	T67M260, T67M260-T3A Post Mod M501	Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
111	Fuel Servo Idle Mixture Setting	1 16.9.96	All T67 a/c equipped with Lycoming RSA-5-AB1 fuel injection systems (T67M260, T67M260-T3A)	Highly Recommended	N/A	SAL
112	Colour Scheme Approval	1 27.8.96	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
113	Inspection of SAB nose leg scissor pivot	1 10.1.97	T67B, T67C Pre Mod M468, T67M, T67M-MkII Pre Mod M468 T67M200	Essential	N/A	SAL
114	Inspection of King KT76A Transponders	1 23.9.96	All T67 Series A/C fitted with KT76A ATC Transponders	Recommended	N/A	SAL
115	Inspection of left hand pilots throttle pushrod	1 2.10.96	T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
116	Lycoming SB No.527B recall of piston pin - Part No. LW-14077	1 10.1.97	T67C Series, T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Essential	N/A	SAL
117	Inspection of trim motor wiring for chafing	1 Not yet issued	T67C Post Mod M443 (Electric Trim) T67M260 (except Works No.2072) T67M260-T3A	Highly Recommended	N/A	SAL
118	Inspection of fuel servo throttle and mixture lever extensions for movement and wear	1 9.4.99	T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
119	Lycoming S.B. No.525A Inspection of high pressure fuel pump P/N LW-15473	1 Not yet issued	T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	FAA Mandatory	FAA Priority Letter AD96-23-03	SAL
120	Inspection of Rudder Bar Support Brackets (NOT NOW AVAILABLE)	1 10.1.97	T67B, T67C Series T67M (Works No.1999 not applicable) T67M-MkII, T67M200 T67M260, T67M260-T3A	Mandatory	012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	2 31.1.97	T67B, T67C Series T67M (Works No.1999 not applicable) T67M-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	3 12.5.97	T67B, T67C Series T67M (Works No.1999 not applicable) T67M-MkII, T67M200 T67M260, T67M260-T3A	Mandatory	012-01-97	CAA
120	Inspection of Rudder Bar Support Brackets	4 22.01.09	T67B, T67C Series T67M (Works No.1999 not applicable) T67M-MkII, T67M200 T67M260, T67M260-T3A	This SB is subject of Airworthiness Directive	EASA AD 2009-0013	CAA/EASA

S.B. No.	Title	Issue/ Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
121	Introduction of SAB Type Nose Undercarriage Leg	1 17.3.97	Pre Mod M425 & Pre Mod M468 a/c ie SAB type undercarriaged T67A, T67B, T67C Series, T67M T67M-MkII, T67M200	Mandatory	010-03-097	CAA
122	Dry Air Pump Coupling Service Life Limitation	1 27.7.97	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
123	Lycoming Service Bulletin/Instruction/Letter Listings	1 24.6.97	T67M260, T67M260-T3A	Essential	N/A	SAL
125	Inspection of Wiring Looms at Rear of Instrument Panel for Chafing	1 27.9.97	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Essential	N/A	SAL
125	Inspection of Wiring Looms at Rear of Instrument Panel for Chafing	2 02.10.02	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260, T67M260-T3A	Essential	N/A	SAL
126	Inspection of Port Rudder Bar for Chafing	1 27.9.97	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
126	Inspection of Port Rudder Bar for Chafing	2 13.3.98	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	1 17.7.97	T67A, T67B, T67M	Mandatory	005-07-97	CAA
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	2 12.12.03	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	005-07-97	CAA
127	Inspection of Aluminium Fittings for Exfoliation Corrosion	3 10.07.04	T67A, T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	G-2004-0013/EASA AD 2004-6425	EASA
128	Inspection of Placard Reading "This Aircraft is Certified VFR IFR Day or Night"	1 16.04.97	T67M260-T3A	Essential	N/A	SAL
129	Hoffmann SB 61-11-03 E9 Inspection for Wear and Leakage on Spacer	1 12.5.97	T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL
129	Hoffmann SB 61-11-03 E9A Inspection for Wear and Leakage on Spacer	2 17.9.97	T67M200, T67M260, T67M260-T3A	Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
130	Inspection of Rudder Pedals for Adjustment Restriction	1 13.7.97	T67B T67C Series (excluding Works No.1999) T67M-MkII, T67M200 T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
130	Inspection of Rudder Pedals for Adjustment Restriction	2 12.3.99	T67B T67C Series (excluding Works No.1999) T67M-MkII, T67M200 T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
131	Inspection for Centre Console Fixing Screw Fouling Electric Trim System	1 27.9.97	T67M260-T3A T67M260 (Not Works No.2072) T67C Post Mod M443 (Electric Trim)	Highly Recommended	N/A	SAL
131	Inspection for Centre Console Fixing Screw Fouling Electric Trim System	2 20.5.98	T67M260-T3A T67M260 (Not Works No.2072) T67C Post Mod M443 (Electric Trim)	Highly Recommended	N/A	SAL
132	Inspection for Water in Bump Stop	1 12.9.97	T67M260, T67M200 (Post Mod M675)	Mandatory	002-09-97	CAA
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	1 27.9.97	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260, T67M260-T3A	Essential	N/A	SAL
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	2 13.3.98	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
133	Inspection of Flap Lever Pivot Attaching Point for Cracking	3 01.07.06	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260 (Post Mod M950 Electric Flapped aircraft N/A), T67M260-T3A	Recommended	N/A	SAL
134	Woodward Service Bulletin Listing	1 27.8.97	T67M260, T67M260-T3A	Essential	N/A	SAL
135	Hoffmann Service Bulletin/Letter Listing	1 27.8.97	T67M260, T67M260-T3A	Essential	N/A	SAL
136	Fairey Hydraulic Service Bulletin Listing	1 27.8.97	T67M260, T67M260-T3A	Essential	N/A	SAL
137	Bendix King Service Bulletin Listing	1 27.8.97	T67M260, T67M260-T3A	Essential	N/A	SAL
138	Inspection of ECS Frame 2 Bay for Corrosion	1 12.9.97	T67M260 T67M260-T3A Post Mod M501A	Essential	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
139	Inspection of Steering Arm on Fairey Hydraulics Nose Leg	1 12.9.97	T67M260, T67M260-T3A Post Mod M468 T67C & T67M-MkII Post Mod M791 T67M-MkII	Mandatory	003-09-97	CAA
139	Inspection of Steering Arm on Fairey Hydraulics Nose Leg	2 20.10.00	T67M260, T67M260-T3A Post Mod M468 T67C & T67M-MkII Post Mod M791 T67M-MkII	Mandatory	003-09-97	CAA
141	Recommended Stiffnut Maintenance Procedures and Clarification of Existing Maintenance Manual Screw/Bolt Torque Values	1 25.2.00	T67A, T67B, T67C Series, T67M T67M-MkII T67M200 T67M260 T67M260-T3A	Recommended	N/A	SAL
142	Inspection for Correct Elevator Trim Tab Indication	1 27.8.97	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
143	Fairey Hydraulics Main Undercarriage Backlash Check	1 27.9.97	Post Mod M468 equipped aircraft T67B, T67C Series, T67M, T67M-MkII, T67M200	Highly Recommended	N/A	SAL
143	Fairey Hydraulics Main Undercarriage Backlash Check	2 9.3.99	Post Mod M468 equipped aircraft T67B T67C Series, T67M, T67M-MkII, T67M200	Highly Recommended	N/A	SAL
144	Trim Tab Drive Pin Check	1 12.2.98	T67M260 T67M260-T3A	Essential	N/A	SAL
145	Inspection and Replacement of Centring Roller Retaining Rivet with Pin	1 17.7.98	T67M260 & T67M260-T3A Post Mod M468 T67C & T67M-MkII & Post Mod M791 T67M-MkII	Highly Recommended	N/A	SAL
147	SAB Undercarriage Nosewheel Steering Adaptor Inspection	1 24.9.98	Pre Mod M468 (Introduction of Fairey Undercarriage T67B, T67C Series T67M, T67M-MkII, T67M200	Highly Recommended	N/A	SAL
150	Inspection of Elevator Lever Pivot Stiffnut at Frame 7	1 9.12.97	T67A, T67B, T67C Series, T67M T67M-MkII, T67M200, T67M260, T67M260-T3A	Mandatory	002-12-97	CAA
151	Inspection of Canopy Slide Lock Spring Dimensions	1 25.6.98	Post Mod M283 T67M-MkII & T67M200 T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
152	Airborne ILS (Localiser) VOR and VHF Communications - Improved FM Broadcast Interference Immunity Standards/Placarding	1 23.3.98	T67A, T67B, T67C Series, T67M T67M-MkII T67M200 T67M260 and T67M260-T3A operating within Europe, Africa, Russia or the Middle East.	Essential	N/A	SAL
152	Airborne ILS (Localiser) VOR and VHF Communications - Improved FM Broadcast Interference Immunity Standards/Placarding	2 02.08.02	T67A, T67B, T67C Series, T67M T67M-MkII T67M200 T67M260 and T67M260-T3A operating within Europe, Africa, Russia or the Middle East.	Essential	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
153	SAB Undercarriage Nosewheel Fork Inspection	1 24.9.98	Pre Mod M468 (Introduction of Fairey Undercarriage T67B, T67C Series, T67M T67M-MkII, T67M200	Recommended	N/A	SAL
153	SAB Undercarriage Nosewheel Fork Inspection	2 30.04.03	T67A Post Mod M136A (SAB T9S), Pre Mod M468 and M791 (Introduction of Fairey Undercarriage) T67B, T67C Series, T67M, T67M-MkII, T67M200	Recommended	N/A	SAL
154	Inspection for Clearance Between SAB Undercarriage Noseleg Steering Pushrod and Engine Mounting Frame	1 21.8.98	Pre Mod M468 and M791 T67A T67B T67C Series, T67M, T67-MkII, T67M200	Highly Recommended	N/A	SAL
155	Inspection for Foul Between Canopy Slide Rail Pivot Bolt and Fuselage Splash Shields	1 21.8.98	T67M-MkII, T67M260 T67M260-T3A Post Mod M129 T67C, T67M and T67M200	Highly Recommended	N/A	SAL
156	Inspection for Engine/Propeller Control Foul with Forward Console	1 21.8.98	T67M260 T67M260-T3A	Recommended	N/A	SAL
157	Five Year Fuel Tank Inspection	1 25.6.98	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
157	Five Year Fuel Tank Inspection	2 04.2.00	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
157	Five Year Fuel Tank Inspection	3 19.03.01	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
157	Five Year Fuel Tank Inspection	4 15.04.05	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
157	Five Year Fuel Tank Inspection	5 26.01.07	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260 (Pre and Post Mod M945)	Essential	N/A	SAL
158	Inspection of Rudder for Ceconite Fabric Debonding	1 25.6.87	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
159	Inspection of Stainless Steel Brake Pipes for Correct Bonding	1 20.1.00	T67M260 T67M260-T3A, plus Post Mod M585, T67B, T67C, T67M, T67Mk-II T67M200	Highly Recommended	N/A	SAL
160	Inspection of Lower Undercarriage Mounting Blocks for Water Ingress	1 13.4.99	T67B, T67C, T6M, T67M-MkII T67M200	Essential	N/A	SAL
161	Fuel Tank Vent Pipe Check	1 29.10.99	T67C Post Mod M156 T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
161	Fuel Tank Vent Pipe Check	2 23.3.01	T67C Post Mod M156 T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
162	Inspection of Pitot Tube Inlet Pipe	1 27.8.99	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
162	Inspection of Pitot Tube Inlet Pipe	2 23.3.01	T67B, T67C Series, T67M, T67M-MkII T67M200, T67M260 T67M260-T3A	Essential	N/A	SAL
163	Inspection of Fuel Valve Torque Shaft Universals	1 11.10.99	T67C Post Mod M156, T67M-MkII, T67M200, T67M260 and T67M260-T3A Pre Mod M830	Highly Recommended	N/A	SAL
163	Inspection of Fuel Valve Torque Shaft Universals	2 13.11.08	T67C Post Mod M156, T67M-MkII, T67M200, T67M260 Pre Mod M945 and T67M260-T3A	Highly Recommended	N/A	SACL
164	Hoffmann Service Letter 61-12-04 SL E4B Introduction of Leading Edge Erosion Film	1 8.12.99	T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
165	Inspection for Water in Leading Edge of Rudder Plus Addition of Drain Hole	1 20.1.00	T67B, T67C, T67M T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
165	Inspection for Water in Leading Edge of Rudder Plus Addition of Drain Hole	2 28.3.01	T67B, T67C, T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Mandatory	005-03- 2001	CAA
166	Hoffmann 61-10-03 SB E1W Listing TBO of Hoffmann Variable Pitch Propellers	1 8.12.99	T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
166	Hoffmann 61-10-03 SB E1W Listing TBO of Hoffmann Variable Pitch Propellers	2 06.06.03	T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
167	Inspection of external aileron and flap drive pushrod for cracking	1 1.8.00	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Essential	N/A	SAL
168	Inspection of Cockpit Floor Beneath Port Rudder Bar Support Bracket	1 19.9.00	T67B, T67C, T67M, T67M-MkII, T67M200 T67M260, T67M260-T3A	Recommended	N/A	SAL
169	Inspection of Engine Intake Duct Mesh and Alternate Air Door	1 27.7.00	T67M, T67M-MkII	Essential	N/A	SAL
169	Inspection of Engine Intake Duct Mesh and Alternate Air Door	2 18.02.05	Part A Post Mod M595, Pre & Post Mod M760 T67M, T67M-MkII. Part B T67M260 (Pre Mod M818) & T67M260-Not applicable to Works Nos 2261, 2266 & subs).	Essential	N/A	SAL
170	Inspection of Control Column Aileron Stop Bolt, Mounting Plate and Rivnut	1 28.3.01	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
171	Inspection of Main Undercarriage Top Mounting Collars	1 28.3.01	T67M-MkII (Post Mod M835), T67M200 (Post Mod M914), T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
172	Inspection of Flap Drive Torque Tube	1 28.3.01	T67A, T67B, T67C, T67M, T67M-MkII, T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL

SERVICE BULLETIN INDEX

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
172	Inspection of Flap Drive Torque Tube	2 22.8.02	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260 (Pre Mod M950) T67M260-T3A	Highly Recommended	N/A	SAL
172	Inspection of Flap Drive Torque Tube	3 23.12.03	T67A, T67B, T67C, T67M, T67M-MkII T67M200 T67M260 (Pre Mod M950), T67M260-T3A	Highly Recommended	N/A	SAL
173	Canopy Latch Assembly Covers	1 15.05.01	Post Mod M129 T67C, T67M, T67M-MkII, T67M200, T67M260 and T67M260-T3A	Highly Recommended	N/A	SAL
174	Hoffmann 61-11-03 E13 Propeller Pitch Change Mechanism Screw Modification	1 27.6.01	T67M200 T67M260, T67M269T3A	Essential	N/A	SAL
175	Inspection of Control Column Housing Brazing	1 11.7.02	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Mandatory	005-07-2002	CAA
176	Inspection for Fitment of Correct Stiffnut on Nosewheel Axle	1 09.07.02	Post Mod M468 T67C & T67M-MkII Post Mod M791 T67M-MkII T67M260, T67M260-T3A	Essential	N/A	SAL
177	Inspection of Starter and Ground Power Socket Solenoids for Cracking - Frame 5 Avionics Panel Mounted	1 02.10.02	T67M200 T67M260 Post Mod M860 (2261 to 2264, 2266 & 2267)	Essential	N/A	SAL
178	Lycoming SB No. 554 Crankshaft Gear Retaining Bolt Replacement	1 27.11.02	T67M260 T67M260-T3A	Mandatory	-	SAL
178	Lycoming SB No. 554 Crankshaft Gear Retaining Bolt Replacement	2 23.12.03	T67M260 T67M260-T3A	Highly Recommended	N/A	SAL
179	Inspection of Tailplane Attachment Brackets	1 10.12.02	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260 T67M260-T3A All const nos except 2266 and subsequent	Mandatory	001-12-2002	CAA
179	Inspection of Tailplane Attachment Brackets	2 11.04.03	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260 T67M260-T3A All const nos except 2266 and subsequent	Mandatory	001-12-2002	CAA
179	Inspection of Tailplane Attachment Brackets	3 20.01.05	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260 T67M260-T3A	This SB is subject of Airworthiness Directive	G-2005-0004/EASA AD 2005-564	CAA
179	Inspection of Tailplane Attachment Brackets	4 15.03.07	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260	This SB is subject of Airworthiness Directive	G-2005-0004/EASA AD 2005-564	CAA

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
180	Inspection of Alternator/Starter Wiring Loom P-Clipping at Engine	1 30.04.03	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Mandatory	005-04-2003	CAA
181	Airborne Service Letters	1 12.08.03	T67A, T67B, T67C, T67M, T67M-MkII T67M200, T67M260, T67M260-T3A	Highly Recommended	N/A	SAL
183	Inspection of Tailplane Aluminium Fittings for Exfoliation Corrosion	1 06.10.05	T67A	This SB is subject of Airworthiness Directive	G-2005-0032/EASA AD 2005-6366	CAA
184	Inspection and Wire locking of Fwd Quadrant Engine Control Spindle CV Tension Pin	1 31.07.06	T67M200 Post Mod M915, T67M260 and T67M260-T3A	Highly Recommended	N/A	SACL
185	Inspection for and Prevention of Water into NACA Air Intake	1 05.09.07	T67M200 Post Mod M915, T67M260 and T67M260-T3A (Post Mod M566)	Highly Recommended	N/A	SACL
186	Inspection of Rudder Navigation Light Wiring for Chaffing	1 05.09.07	T67M200 Post Mod M915 and T67M260 Pre Mod M950	Highly Recommended	N/A	SACL
186	Inspection of Rudder Navigation Light Wiring for Chaffing	2 10.06.08	T67B, T67C Series, T67M, T67M-MkII, T67M200, T67M260 Pre Mod M950 & T67M260-T3A.	Highly Recommended	N/A	SACL
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	1 09.03.07	T67M200 (Works Nos. 2264 and 2265 only) and T67M260	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	2 10.05.07	T67M200 (Works Nos. 2264 and 2265 only), T67M260 and T67M260-T3A	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	3 16.10.07	T67M200 (Works Nos. 2264 and 2265 only), T67M260 and T67M260-T3A	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	4 22.01.09	T67M200 (Works Nos. 2264 and 2265 only), T67M260 and T67M260-T3A	This SB is subject of Airworthiness Directive	EASA AD 2009-0013	CAA/EASA
187	Inspection for Clearance between Rudder Pedal and Mixture/Prop Speed Bracket. Also includes General Rudder Pedal Clearances	5 14.10.09	T67M200 (Works Nos. 2264 and 2265 only), T67M260 and T67M260-T3A	This SB is subject of Airworthiness Directive	EASA AD 2009-0218	CAA/EASA

S.B. No.	Title	Issue/Date	Applicability	Classification	CAA/EASA A.D. No.	Approval
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	1 09.03.07	T67B, T67C Series, T67M, T67M-MkII T67M200 (excluding Works No. 2264 and 2265)	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	2 10.05.07	T67B, T67C Series, T67M (excluding Works No. 1999), T67M-MkII, T67M200 (excluding Works No. 2264 and 2265)	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	3 16.10.07	T67B, T67C Series, T67M (excluding Works No. 1999), T67M-MkII, T67M200 (excluding Works No. 2264 and 2265)	This SB is subject of Airworthiness Directive	EASA AD 2007-0132	CAA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	4 22.01.09	T67B, T67C Series, T67M (excluding Works No. 1999), T67M-MkII, T67M200 (excluding Works No. 2264 and 2265)	This SB is subject of Airworthiness Directive	EASA AD 2009-0013	CAA/EASA
188	Inspection for Rudder Pedal Clearances Between Rudder Pedals and the Aircraft Structure and Components	5 14.10.09	T67B, T67C Series, T67M (excluding Works No. 1999), T67M-MkII, T67M200 (excluding Works No. 2264 and 2265)	This SB is subject of Airworthiness Directive	EASA AD 2009-0218	CAA/EASA
189	Inspection of Tailplane Attachment Bolt Thread Diameter	1 13.11.08	T67B, T67C Series, T67M, T67M-MkII, T67M260 & T67M260-T3A	Highly Recommended	N/A	SACL